

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE (ER 1130-2-3165)					PAGE 1 OF 1		
					DATE March 2006		
TO: The Record				FROM: U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090			
Shinnecock Inlet, NY Condition Survey					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)			
Shinnecock Inlet	File #45, Page 1 of 1 24 Jan. 2006	200	0.46	10	7.5	5.6	7.1
<b>REMARKS:</b> A shoal having the minimum depths shown above extends across the entire channel width for a length of 450 feet (left outside quarter) to 750 feet (right outside quarter) , commencing approximately 1500 feet seaward of the end of the western jetty.							